
Chapter 11 Figures: Access, Traffic and Transport





Revised Larbrax Wind Farm EIA Report

for Ørsted Onshore UK Ltd




Figure 11.1: Study Area

Site boundary Study area

Orsted Pell Frischmann

Source: Pell Frischmann, Ørsted, LUC



Revised Larbrax Wind Farm EIA Report

for Ørsted Onshore UK Ltd



Figure 11.2: Traffic Count Locations

Site boundary


Automatic Traffic Count survey location

Department for Transport count location

Transport Scotland count location

Orsted

Pell Frischmann



Revised Larbrax Wind Farm EIA Report

for Ørsted Onshore UK Ltd



Figure 11.3: Personal Injury Accident Plan

Site boundary


Fatal Personal Injury Accident location

Serious Personal Injury Accident location

Slight Personal Injury Accident location

Orsted

Pell Frischmann



Revised Larbrax Wind Farm EIA Report for Ørsted Onshore UK Ltd



Figure 11.4: Abnormal Indivisible Loads Route

Site boundary

Abnormal Indivisible Loads Route

Pell Frischmann **Orsted**